										=======================================		
Work Order February 8, 2011												Page 1
Revision ID:	03535-15 Wearshoe	-		Accept					Setup	Start Stop		
Start Date: 2 Required Date: 2 Reference:	/08/11 /22/11	Start Qty: 6.00 Req'd Qty: 6.00		-: =)	Cust Item I Customer:	D:						
• •	Process Plai		Date:			nte:		j	Run	Start Stop		
Sequence ID/ Work Center ID		Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Ins Number Sta	sp. amp
Draw Nbr		sion Nbr					-		٤,			**
D3535 100 Waterjet FLOW CNC Waterjet	Rev	FLOW WATER JET Memo 1-Cut as per Deburr if nec	Dwg D3535 □Dwg cessary	0.00 0.00 Rev: B □Prog Rev:	<u>B</u> ====================================			18	. i(<u>~</u> 3	9-1 <u>5</u>	(G)	
QC Quality Control		QC2- Inspect parts off ma	achine FAI/FAIB	0.00				H3	311 <u>-</u> 2	<u>)-(</u>		

QC8- Inspect parts - second check

0.00

Memo

0.00 Sida/16

Quality Control

	•									
W/O:			W	ORK ORDER CHANG	GES					
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	,	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·								
Part No	;	PAR #:	Fault Cate	egory:	NCR: Y	es N	lo DQ	A:	Date: _	
	R	esolution:	Disposition	on:	QA: N/	C Clos	sed:	***	Date: _	
NCR:			WORK ORD	ER NON-CONFORM	MANCE (N	ICR)				
DATE	STEP	Description of NC			ection B	0		cation	Approval	Approval
DALL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Sect	on C	Chief Eng	QC Inspector
										,
					-					

Work Order ID 66238

'February 8, 2011 8:43:45 AM

Page 2

Item ID:

D3535-15

Accept

Setup Start

Stop

Start

Stop



Revision ID:

Start Date:

Wearshoe Item Name:

Required Date: 2/22/11

2/08/11

Start Qty: 6.00

Req'd Qty: 6.00



Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan: _____ Date: ____

Tooling:

Date:

Date:

Run

QC:

Date: _____

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Tool # Plan

Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

Sequence ID/

Work Center ID

130

Brake NC

Brake NC

Memo

Operation

Description

NC BRAKE

0.00

0.00

- 1-Form on Brake as per Dwg D3535 using Jigs DT8261and DT8326□2-Form joggle as per Dwg D3535 using Jig DT8158□3-Identify as D3535-15

Spillozlie

140

QC

Quality Control

QC5- Inspect part completeness to step on W/O

150

Powdercoat

Powder Coating

Grey Sandtex(Ref:4.3.5.6) per QSI005 4.3

Memo

Memo

m 115108

0.00

6 BR 11-02-25

W/O:	-	The contract of the contract o	W	ORK ORDER CHANG	ES				
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			•						
			·.	·					
Part No	•	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A:	Date: _	L
	R	esolution:	Dispositi	on:	_ QA: N/C C	losed:		Date: _	
NCR:		\	WORK ORE	DER NON-CONFORM	ANCE (NC	R)			
DATE	STEP	Description of NC	In it in I		ion B Sign	0 1	cation		Approval
JAIL	0.5	Section A	Initial	Action Description	Joigii	CX Sec	tion C		OC Inchestor
-			Chief Eng	Chief Eng	Date	, ,	tion C	Chief Eng	QC Inspector
			Chief Eng	Chief Eng	Date)		Cnier Eng	QC Inspector
			Chief Eng	Chief Eng	Date	9		Chief Eng	QC Inspector
			Chief Eng	Chief Eng	Date		uiori C	Chief Eng	QC IIIspector
			Chief Eng	Chief Eng	Date			Chief Eng	QC Inspector
			Chief Eng	Chief Eng	Date			Chief Eng	QC Inspector
			Chief Eng	Chief Eng	Date		iion C	Chief Eng	QC IIISPECIO
			Chief Eng	Chief Eng	Date		iion C	Chief Eng	QC IIISPECIO
			Chief Eng	Chief Eng	Date		uori C	Chief Eng	QC IIISPECIO

Work Order ID 66238

Page 3

February 8, 2011 8:43:45 AM

Item	111.
Hem	117.

D3535-15

Accept



Setup Start



Revision ID:

Start Date:

Item Name:

Wearshoe

2/08/11

Start Otv: 6.00 **Reg'd Oty:** 6.00

Cust Item ID:

Customer:

Stop

Reference:

Approvals:

Process Plan: Date:

Tooling:

Date:

Run

Start

Required Date: 2/22/11

Date:

SPC (Y/N):

Set Up/

Run Hours

Date:

Stop

Sequence ID/ Work Center ID

160

Operation Description

OC3- Inspect Part Finish

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reiect Number

Insp. Stamp

Ouality Control

170

Packaging

Packaging

Memo

0.00

Memo

Identify as per dwg & Stock Location

0.00

180

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

11/02/24 \$t

	. Johnso								
W/O:			WC	RK ORDER CHANGE	ES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A :	Date: _	
	R	esolution:	Disposition	n:	QA: N/C CI	osed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section			cation		Approval
DATE	SILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector
				•					

Picklist Print

February 8, 2011 8:43:44 AM

Work Order ID: 66238

Parent Item: D3535-15

Parent Item Name:

Wearshoe



Start Date: 2/08/11

Required Date: 2/22/11

Page 1

Start Qty: 6.00

Required Qty: 6.00

Comments:

IPP Rev:A New Issue 07-02-15 JLM

IPP Rev:B As per Rev B 07-08-31 JLM Verified By:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S20GA	I	Purchased	No			100	sf	149.5538	1.0205	6.445263			
										MB i	17-15	_	
304/316 .040 Sheet				Location		Loc (Qt <u>y</u>	Loc Code				(,)	
				MAT		149.5	5538					6	
					115953		21.6		_				
					116437	52.3	7538		_	V			
					116623		75.2		1	16633			

W/O:			W	ORK ORDER CHANG	BES		-			
DATE	STEP	PRO	OCEDURE CH	ANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									, -,	
				•						
Part No	:	PAR #:	Fault Cate	egory:	_ NCR	: Yes I	No DQ	A:	Date: _	
	R	esolution:	Disposition	on:	QA:	N/C Clo	sed:		Date: _	
NCR:		1	WORK ORE	DER NON-CONFORM	ANCE	(NCR)			
DATE	STEP	Description of NC			tion B		Verifi	cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Sect	ion C	Chief Eng	QC Inspector
1										
ı										
I		,								
					1					
			·							

DART AEROSPACE LTD	Work Order:	<i>66238</i>
Description: Wearshoe	Part Number:	D3535-15
Inspection Dwg: D3535 Rev: B		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
1.885	+/-0.010	1.888	æ	V	V 1B6Z	
2.000	+/-0.010	7.00)eQ		V	
5.650	+/-0.010	5.650	V		7	
9.150	+/-0.010	9.146	8		1	
14.400	+/-0.010	14,400	Q		7	
19.650	+/-0.010	19.656) 		7	
24.900	+/-0.010	24.900	×		7	
30.150	+/-0.010	30,156	×		٦	
33.650	+/-0.010	33.650	ঠ		7	
35.650	+/-0.010	38.650	بخ		T	
39.150	+/-0.010	39,150	8		7	
Ø0.188	+0.005/-0.001	.191	٠,		V	
24.00	+/-0.030	74.00	×		7	
16.00	+/-0.030	16,00	×		7	
8.00	+/-0.030	00,8	5		T	
5.00	+/-0.030	5.00	8		1	
0.300	+/-0.010	,304	ط		V	
0.300	+/-0.010	304	St.		V	
0.038	+/-0.010	,037	*		V	

Measured by: 3	Audited by:	Prototype Approval:	N/A
Date: 1(-3 - 1	Date: 1/02/16	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	07.05.10	New Issue	KJ/JLM	E


DART


AEROSPACE

USA,

₹ C










42.40.La

DIL HOSE



D3535-31F FLAT PATTERN

22.500 19.000

DETAIL A

#0.188 (TYP 3 PLS)

14.250

9.500


6.000 -

2.000

1.885

UNCONTROLLED (*OP* WORK ORDER WITHOUT NOTICE ENGINEERING RETURN TO

SUBJECT TO AMENDMENT SHOP COPY




PURPOSE

엹

COPIED

- 1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524, 20 CAUGE (0.038 THICK) (REF DART SPEC M304S20GA)
 2) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER QSI 005 4.3
- 3) PART IS SYMMETRICAL ABOUT &
 4) TOLERANCES ARE PER DART QSI 018 UNLESS
 OTHERWISE NOTED
- ALL DIMENSIONS ARE IN INCHES
- BREAK ALL SHARP EDGES TO 0.010 MAX IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER
- 8) SEE PAGE 7 FOR DETAILS AND SECTION



봀

DOCUMENT

 $\overline{\mathbf{s}}$

42.10.60

IN THE ASK

60

3

DART

AEROSPACE PORT HADLOCK,

N

DRAWING NO.

SHEET


Ü SCALE

읶

1:10



07.04.17



D3535-35 BEND DETAIL

UNCONTROLLED COPY SUBJECT TO AMENDMENT WORK ORDER WITHOUT NOTICE ENGINEERING SHOP COPY RETURN TO

돺

DOCUMENT

ᇙ

Copyright © 2006 by DART AEROSPACE USA, IN PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART /

INC.

NOT TO BE USED FOR ANY F

NOT AEROSPACE USA, INC.

PURPOSE

유

COPIED

1) MATERIAL: AISI 304/316 SS SHEET PER AMS 5513 OR AMS 5524, 20 GAUGE (0.038 THICK) (REF DART SPEC M304S20GA)
2) FINISH: POWDER COAT GREY SANDTEX (4.3.5.6) PER


QSI 005 4.3


3) PART IS SYMMETRICAL ABOUT €
4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

5) ALL DIMENSIONS ARE IN INCHES

6) BREAK ALL SHARP EDGES TO 0.010 MAX 7) IDENTIFY WITH DART P/N USING WHITE FINE POINT PAINT MARKER


8) SEE PAGE 7 FOR DETAILS AND SECTION







DESIGN	DRAWN BY	DART	AEROSPACE USA, INC.
CHECKED 44	APPROVED ",/	DRAWING NO.	REV. B
		D3535	SHEET 7 OF 7
DATE	<u></u>	TITLE	SCALE
07.04.17		WEARSHOE	1:1



Copyright © 2006 by DART AEROSPACE USA, INC.

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.